

## Engineering Forum Business Session Agenda

### **Tuesday June 2, 2009**

- 1:30 p.m. – 1:45 p.m. Welcome and Introductions, Gary Miller (Region 6)
- 1:45 p.m. – 2:15 p.m. Strategic Plan Update and membership discussion, co-chairs Hilary Thornton (Region 3) and Gary Miller (Region 6)
- 2:15 p.m. – 2:45 p.m. Energy calculator, history, status update, lessons learned, Mike Gill (Region 9 Superfund Technical Liaison)
- 2:45 p.m. – 3:00 p.m. TSP Fall Meeting Update, Hilary Thornton (Region 3)
- 3:00 p.m. – 3:15 p.m. Break
- 3:15 p.m. – 4:45 p.m. Green Remediation Subcommittee: Update and proposed changes, Raji Josiam (Region 6) and Co-chairs
- 4:45 p.m. – 5:00 p.m. Summary, Co-chairs